

Lexmark Security Advisory:

Revision: 1.2
Last update: 19 September 2025
Public Release Date: 19 September 2025

Summary

A Server-Side Request Forgery (SSRF) vulnerability has been identified in the embedded web server in various Lexmark devices.

References

CVE: CVE-2025-9269

CWE: CWE-918

Details

A Server-Side Request Forgery (SSRF) vulnerability has been identified in the embedded web server in various Lexmark devices. This vulnerability can be leveraged by an attacker to force the device to send an arbitrary HTTP request to a third-party server.

CVSSv4 Base Score 6.9
(CVSS:4.0/AV:N/AC:L/AT:N/PR:N/UI:N/VC:L/VI:N/VA:N/SC:L/SI:N/SA:N)
Impact Subscore: 0.0
Exploitability Subscore: 0.0

CVSSv3 scores are calculated in accordance with CVSS version 4.0 (<https://www.first.org/cvss/user-guide>)

Impact

Successful exploitation of this vulnerability can lead to internal network access / potential data disclosure from a device.

Affected Products

To determine a devices firmware level, select the “Settings”->“Reports”->”Menu Setting Page” menu item from the operator panel. If the firmware level listed under “Device Information” matches any level under “Affected Releases”, then upgrade to a “Fixed Release”.

Lexmark Models	Affected Releases	Fixed Releases
CX950, CX951	CXTLS.250.199 and previous	CXTLS.250.200 and later
XC9525, XC9535	CXTLS.250.199 and previous	CXTLS.250.200 and later
MX953	MXTLS.250.199 and previous	MXTLS.250.200 and later
CX961, CX962, CX963	CXTLS.250.199 and previous	CXTLS.250.200 and later
XC9635, XC9645, XC9655	CXTLS.250.199 and previous	CXTLS.250.200 and later
CS963	CSTLS.250.199 and previous	CSTLS.250.200 and later
CX833	CXTLS.250.199 and previous	CXTLS.250.200 and later

XC8355	CXTLS.250.199 and previous	CXTLS.250.200 and later
MS531, MS631	MSNSN.250.199 and previous	MSNSN.250.200 and later
MS632, M3350	MSTSN.250.199 and previous	MSTSN.250.200 and later
MX532, MX632, XM3350	MXTSN.250.199 and previous	MXTSN.250.200 and later
CS531, C2335	CSNGV.250.199 and previous	CSNGV.250.200 and later
CS632	CSTGV.250.199 and previous	CSTGV.250.200 and later
CX532, CX635, XC2335	CXTGV.250.199 and previous	CXTGV.250.200 and later
CX930, CX931, CX942, CX943, CX944	CXTPC.250.199 and previous	CXTPC.250.200 and later
XC9325, XC9335, XC9445, XC9455, XC9465	CXTPC.250.199 and previous	CXTPC.250.200 and later
CS943	CSTPC.250.199 and previous	CSTPC.250.200 and later
MX432	MXTCT.250.199 and previous	MXTCT.250.200 and later
XM3142	MXTCT.250.199 and previous	MXTCT.250.200 and later
MX931	MXTPM.250.199 and previous	MXTPM.250.200 and later
CX730, CX735, CX737	CXTMM.250.199 and previous	CXTMM.250.200 and later
XC4342, XC4352	CXTMM.250.199 and previous	CXTMM.250.200 and later
CS730, CS735, CS737	CSTMM.250.199 and previous	CSTMM.250.200 and later
C4342, C4352	CSTMM.250.199 and previous	CSTMM.250.200 and later
MS321, MS421, MS521, MS621	MSNGM.250.199 and previous	MSNGM.250.200 and later
M1242, M1246	MSNGM.250.199 and previous	MSNGM.250.200 and later
B2338, B2442, B2546, B2650	MSNGM.250.199 and previous	MSNGM.250.200 and later
MS622	MSTGM.250.199 and previous	MSTGM.250.200 and later
M3250	MSTGM.250.199 and previous	MSTGM.250.200 and later
MX321	MXNGM.250.199 and previous	MXNGM.250.200 and later
MB2338	MXNGM.250.199 and previous	MXNGM.250.200 and later
MX421, MX521, MX522, MX622	MXTGM.250.199 and previous	MXTGM.250.200 and later
XM1242, XM1246, XM3250	MXTGM.250.199 and previous	MXTGM.250.200 and later
MB2442, MB2546, MB2650	MXTGM.250.199 and previous	MXTGM.250.200 and later
MS725, MS821, MS823, MS825	MSNGW.250.199 and previous	MSNGW.250.200 and later
B2865	MSNGW.250.199 and previous	MSNGW.250.200 and later
MS822, MS826	MSTGW.250.199 and previous	MSTGW.250.200 and later
M5255, M5270	MSTGW.250.199 and previous	MSTGW.250.200 and later
MX721, MX722, MX725, MX822, MX826	MXTGW.250.199 and previous	MXTGW.250.200 and later
XM5365, XM5370, XM7355, XM7370	MXTGW.250.199 and previous	MXTGW.250.200 and later
MB2770	MXTGW.250.199 and previous	MXTGW.250.200 and later
CS622	CSTZJ.250.199 and previous	CSTZJ.250.200 and later
C2240	CSTZJ.250.199 and previous	CSTZJ.250.200 and later
CS421, CS521	CSNZJ.250.199 and previous	CSNZJ.250.200 and later
C2325, C2425, C2535	CSNZJ.250.199 and previous	CSNZJ.250.200 and later
CX522, CX622, CX625	CXTZJ.250.199 and previous	CXTZJ.250.200 and later

XC2235, XC4240	CXTZJ.250.199 and previous	CXTZJ.250.200 and later
MC2535, MC2640	CXTZJ.250.199 and previous	CXTZJ.250.200 and later
CX421	CXNZJ.250.199 and previous	CXNZJ.250.200 and later
MC2325, MC2425	CXNZJ.250.199 and previous	CXNZJ.250.200 and later
B2236	MSLSG.230.466 and previous	MSLSG.230.467 and later
MB2236	MXLSG.230.466 and previous	MXLSG.230.467 and later
MS331, MS431, MS439	MSLBD.230.466 and previous	MSLBD.230.467 and later
M1342	MSLBD.230.466 and previous	MSLBD.230.467 and later
B3442, B3340	MSLBD.230.466 and previous	MSLBD.230.467 and later
XM1342	MXLBD.230.466 and previous	MXLBD.230.467 and later
MX331, MX431	MXLBD.230.466 and previous	MXLBD.230.467 and later
MB3442	MXLBD.230.466 and previous	MXLBD.230.467 and later
C3426	CSLBN.230.466 and previous	CSLBN.230.467 and later
CS431, CS439	CSLBN.230.466 and previous	CSLBN.230.467 and later
CS331	CSLBL.230.466 and previous	CSLBL.230.467 and later
C3224, C3326	CSLBL.230.466 and previous	CSLBL.230.467 and later
C2326	CSLBN.230.466 and previous	CSLBN.230.467 and later
MC3426	CXLBN.230.466 and previous	CXLBN.230.467 and later
CX431	CXLBN.230.466 and previous	CXLBN.230.467 and later
XC2326	CXLBN.230.466 and previous	CXLBN.230.467 and later
MC3426	CXLBN.230.466 and previous	CXLBN.230.467 and later
MC3224, MC3326	CXLBL.230.466 and previous	CXLBL.230.467 and later
CX331	CXLBL.230.466 and previous	CXLBL.230.467 and later
CX820, CX825, CX827, CX860	CXTPP.230.466 and previous	CXTPP.230.467 and later
XC6152, XC6153, XC8155, XC8160, XC8163	CXTPP.230.466 and previous	CXTPP.230.467 and later
CS820, CS827	CSTPP.230.466 and previous	CSTPP.230.467 and later
C6160	CSTPP.230.466 and previous	CSTPP.230.467 and later
CS720, CS725, CS727, CS728	CSTAT.230.466 and previous	CSTAT.230.467 and later
C4150	CSTAT.230.466 and previous	CSTAT.230.467 and later
CX725, CX727	CXTAT.230.466 and previous	CXTAT.230.467 and later
XC4140, XC4143, XC4150, XC4153	CXTAT.230.466 and previous	CXTAT.230.467 and later
CS921, CS923, CS927	CSTMH.230.466 and previous	CSTMH.230.467 and later
C9235	CSTMH.230.466 and previous	CSTMH.230.467 and later
CX920, CX921, CX922, CX923, CX924	CXTMH.230.466 and previous	CXTMH.230.467 and later
XC9225, XC9235, XC9245, XC9255, XC9265	CXTMH.230.466 and previous	CXTMH.230.467 and later
MS315, MS415, MS417	LW90.TL2.P224 and previous	LW90.TL2.P225 and later
MS510, MS517, MS610dn, MS617	LW90.PR2.P224 and previous	LW90.PR2.P225 and later
M1140+, M1145, M3150dn	LW90.PR2.P224 and previous	LW90.PR2.P225 and later
MS610de, M3150de	LW90.PR4.P224 and previous	LW90.PR4.P225 and later
MX410, MX417, MX510, MX511, MX517	LW90.SB4.P224 and previous	LW90.SB4.P225 and later

XM1140, XM1145	LW90.SB4.P224 and previous	LW90.SB4.P225 and later
MX610, MX611, MX617	LW90.SB7.P224 and previous	LW90.SB7.P225 and later
XM3150	LW90.SB7.P224 and previous	LW90.SB7.P225 and later
MS710, MS711, MS810dn, MS811, MS812dn, MS817, MS818	LW90.DN2.P224 and previous	LW90.DN2.P225 and later
M5163dn	LW90.DN2.P224 and previous	LW90.DN2.P225 and later
MS810de	LW90.DN4.P224 and previous	LW90.DN4.P225 and later
M5155, M5163de	LW90.DN4.P224 and previous	LW90.DN4.P225 and later
MS812de	LW90.DN7.P224 and previous	LW90.DN7.P225 and later
M5170	LW90.DN7.P224 and previous	LW90.DN7.P225 and later
MX710, MX711, MX717, MX718, MX810, MX811, MX812	LW90.TU.P224 and previous	LW90.TU.P225 and later
XM5163, XM5170, XM5263, XM5270, XM7155, XM7163, XM7170, XM7263, XM7270	LW90.TU.P224 and previous	LW90.TU.P225 and later
MS911	LW90.SA.P224 and previous	LW90.SA.P225 and later
MX910, MX911, MX912	LW90.MG.P224 and previous	LW90.MG.P225 and later
XM9145, XM9155, XM9165	LW90.MG.P224 and previous	LW90.MG.P225 and later
CX510, CX517	LW90.GM7.P224 and previous	LW90.GM7.P225 and later
XC2132	LW90.GM7.P224 and previous	LW90.GM7.P225 and later
XC2130	LW90.GM4.P224 and previous	LW90.GM4.P225 and later
CS510, CS517	LW90.VY4.P224 and previous	LW90.VY4.P225 and later
C2132	LW90.VY4.P224 and previous	LW90.VY4.P225 and later
CX410, CX417	LW90.GM4.P224 and previous	LW90.GM4.P225 and later
MS310, MS312, MS317, MS410	LW80.PRL.P260 and previous	LW80.PRL.P261 and later
M1140	LW80.PRL.P260 and previous	LW80.PRL.P261 and later
MX310, MX317	LW80.SB2.P260 and previous	LW80.SB2.P261 and later
XM1135	LW80.SB2.P260 and previous	LW80.SB2.P261 and later
CS310, CS317	LW80.VYL.P260 and previous	LW80.VYL.P261 and later
CS410, CS417	LW80.VY2.P260 and previous	LW80.VY2.P261 and later
CX310, CX317	LW80.GM2.P260 and previous	LW80.GM2.P261 and later

Obtaining Updated Software

To obtain firmware that resolves this issue or if you have special code, please contact Lexmark's Technical Support Center at <http://support.lexmark.com> to find your local support center.

Workarounds

Lexmark recommends a firmware update if your device has affected firmware.

Exploitation and Public Announcements

Lexmark is not aware of any malicious use against Lexmark products of the vulnerability described in this advisory.

Lexmark would like to thank the following people working for bringing this issue to our attention:

- Chen Independent Security Researcher

Status of this Notice:

THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS AND IS PROVIDED WITHOUT ANY EXPRESS OR IMPLIED GUARANTEE OR WARRANTY WHATSOEVER, INCLUDING BUT NOT LIMITED TO THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR USE OR PURPOSE. LEXMARK RESERVES THE RIGHT TO CHANGE OR UPDATE THIS DOCUMENT AT ANY TIME.

Distribution

This advisory is posted on Lexmark's web site at <http://support.lexmark.com/alerts>
Future updates to this document will be posted on Lexmark's web site at the same location.

Revision History

<u>Revision</u>	<u>Date</u>	<u>Reason</u>
Draft_0.1	19 August 2025	Initial Draft
1.1	17 September 2025	Correct Firmware Versions for FW23 products
1.2	19 September 2025	Correct EC9 Firmware Versions